Order-No.: DD+DIS291.00E

1 Piece UBKG6 MA1

October 2000

Field Service Bulletin No. 13 for

ADC Solo

Type 5155

Classification			When		
Safety relevant	Reliability	New function	Immediately	Next service	As required
	X			X	

Damage of large cassettes when being removed from digitizer

Problem

Large cassettes may get damaged and plastic shavings may fall into the digitizer (scan unit).

Reason

If large format cassettes are being removed from the input slot in a tilted position, the upper edge of the cassette rubs against the sharp metal plate at the top of the slot (part of frame).
See figures below for details.

Improper removal of a large format cassette.
Do always remove horizontally !

View inside the digitizer:
The white circle marks the place where the cassette touches the sharp metal frame of the machine.

Solution

a) Mount an edge protection (CM+0.0000.01.105; 1piece = 1meter) on the metal plate (approximate length 10 cm).

b) Advise the operator how to remove large cassettes properly.